σ	Ŋ	4	ω	N	H	
BRS	BRS	BRS	BRS	BRS	BRS	Type
18	1	Ш	8	29	6	Hits
automat\$3 with test\$3 with electrical same manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial)	"4351013".PN.	"4358732".PN.	automat\$3 with test\$3 with electrical with manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial)	automat\$3 with test\$3 with electrical with manufacture\$1	automat\$3 with test\$3 with factory with information	Search Text
US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	USPAT; USOCR	USPAT; USOCR	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/06/14 10:56	2005/06/14	2005/06/14 10:54	2005/06/14 11:48	2005/06/14	2005/06/14 10:50	Time Stamp
			-			Comments

0	ហ	4	ω	N	1	
·						Error Definitio n
						Lo Errors
S7	S 5	S 4	S	S 2	S	Ref

	Туре	Hits	Search Text	DBs	Time Stamp	Comments
7	BRS	N	automat\$3 with test\$3 with electrical same manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial) and control\$4 with command\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14	
σ	BRS	39	automat\$3 with test\$3 with electrical and manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial) and control\$4 with command\$1 and (file\$1 or database)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14 11:00	
9	BRS	₽.	automat\$3 with test\$3 with electrical and manufacture\$1 and correct with (ID or identification\$1 or identifier\$1 or serial) and control\$4 with command\$1 and stored with (file\$1 or database)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14	

9	®		
•	ω	7	
			Error Definitio n
			Errors
S11	89	88	Ref

	ŏ	s t	est\$3 with	DBs US-PGPUB;	~ "
10	BRS	<u>1</u> 5	with test\$3 with 1 and re\$1 and (ID or ation\$1 or serial) ol\$4 with and stored with r database)	US-P USPA JPO; IBM_	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB
7 7	BRS	P	automat\$3 with test\$3 with electrical and manufacture\$1 and (verify\$3 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial) and control\$4 with command\$1 and stored with (file\$1 or database)		US-PGPUB; USPAT; EPO; 2005/ JPO; DERWENT; 11:02 IBM_TDB
12	BRS	U	automat\$3 with test\$3 with electrical and manufacture\$1 and (verify\$3 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial)	US-P USPA JPO; IBM_	US-PGPUB; USPAT; EPO; 2005/06/14 JPO; DERWENT; 11:05 IBM_TDB

12	11	10	
			Error Definitio n
			Errors
\$13	S12	S10	Ref

	Туре	Hits	Search Text	DBs	Time Stamp	Comments
			automat\$3 with test\$3 instrument\$1 same electrical and	US-PGPUB;		
13	BRS	50249	e\$1 and or vạlidat\$3)	USPAT; EPO; JPO; DERWENT;	2005/06/14 11:05	
_			Or .	:DB		
•			ific	I		
			identifier\$1 or serial)			
			automat\$3 with test\$3 with			
			instrument\$1 same			
-			electrical and	US-PGPUB;		
7			manufacture\$1 and	USPAT; EPO;	2005/06/14	
‡ -	020	F	(verify\$3 or validat\$3)	JPO; DERWENT;	11:06	
			with (ID or	IBM_TDB		
			identification\$1 or			
			identifier\$1 or serial)			
			automat\$3 with test\$3 with			
_			instrument\$1 and			
-			electrical with voltage\$1	US-PGPUB;		
u 7			and manufacture\$1 and	USPAT; EPO;	2005/06/14	
Ĺ	70		(verif\$7 or validat\$3)	JPO; DERWENT;	11:09	
			with (ID or	IBM TDB		
	-		identification \$1 or			
•			identifier\$1 or serial)			

15	14	13	
			Error Definitio n
			Errors
S16	S15	S14	Ref

	Туре	Hits	Search Text	DBs	Time Stamp
16	BRS	N	automat\$3 with test\$3 and electrical with voltage\$1 with instrument\$1 and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14 11:09
17	BRS	1	automat\$3 with test\$3 and electrical with voltage\$1 and hi-pot with test\$3 with instrument\$1 and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14
18	BRS	1	automat\$3 with test\$3 and electrical with voltage\$1 and hi-pot with test\$3 with instrument\$1 and manufacture\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14
19	BRS	1	automat\$3 with test\$3 and hi-pot with test\$3 with instrument\$1 and manufacture\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	2005/06/14 11:10

19	18	17	16	
				Error Definitio n
				Errors
S20	S19	S18	S17	Ref

00	Type		ch Text	DBs GPUB; T; EPO	
0	BRS	42	with test\$3 with ment\$1	BARR	
21	BRS	ы	automat\$3 with test\$3 and electrical with voltage\$1 and (high-potential or (high adj potential) or hi-pot) with test\$3 with instrument\$1 and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or identification\$1 or	US-PGPU USPAT; JPO; DE IBM_TDB	US-PGPUB; USPAT; EPO; 2005/06/14 JPO; DERWENT; 11:13 IBM_TDB
22	BRS	2	automat\$3 with test\$3 and electrical with voltage\$1 and (high-potential or (high adj potential) or hi-pot) with test\$3 with instrument\$1	US-PGPUB; USPAT; EP JPO; DERW IBM_TDB	US-PGPUB; USPAT; EPO; 2005/06/14 JPO; DERWENT; 11:13 IBM_TDB
23	BRS	U	electrical with voltage\$1 and (high-potential or (high adj potential) or hi-pot) with test\$3 with instrument\$1	US-PGPU USPAT; JPO; DE	-PGPUB; PAT; EPO; 2005/06/16 O; DERWENT; 09:33 M_TDB

23	22	21	20	
				Error Definitio n
				Errors
S24	S 2 3	S22	S21	Ref

	Type	Hits	Search Text	DBs	Time Stamp
24	BRS	25	"4434489".uref.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	2005/06/14 11:18
25	BRS	0	"4434489".uref. and electric\$2 with instrument\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14
26	BRS	ω	"4434489".uref. and electric\$4 and instrument\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	2005/06/14 11:19
27	BRS	162	automat\$3 with test\$3 same electrical and manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14
28	BRS	æ	automat\$3 with test\$3 same electrical and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial) with number\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14

22 88	27	26	25	24	Definitio Errors
- V	٠ د	W	S	S	
S 2 8	S27	S26	S 25	86	# P

Туре	Hits	Search Text	DBs	Time Stamp
29 BRS	87	automat\$3 with test\$3 and electrical and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or identifier\$1 or serial) with number\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14
30 BRS	63	automat\$3 with test\$3 and electrical and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or serial) with number\$1 or serial) with (ID or identification\$1 or serial) with (ID or identification\$1 or identification\$1 or serial)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14

30	29	
		Error Definitio n
		Errors
S30	S29	Ref

	Туре	Hits	Search Text	DBs	Time Stamp	Comments
31	BRS	12	automat\$3 with test\$3 and electrical and manufacture\$1 and (verif\$7 or validat\$3) with (ID or identification\$1 or serial) with number\$1 and read\$3 with (ID or identification\$1 or identification\$1 or identification\$1 or serial) with (file\$1 or serial) or folder\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14	
32	BRS	0	automat\$3 with test\$3 and voltage\$1 with tolrance\$1 and test\$3 with (cod\$3 or program\$1 or software) with instrument\$1 with port\$1 with operating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14	
ω	BRS	1	automat\$3 with test\$3 and voltage\$1 with tolerance\$1 and test\$3 with (cod\$3 or program\$1 or software) with instrument\$1 with port\$1 with operating	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/14	

	ω ω	32	31	
				Error Definitio n
				Errors
ŀ	S33	S32	S 3 1	Ref

	Type		with test\$3 and th (cod\$3 or	DBs UB; EPO;	Time Stamp
34	BRS	Н	\$3 with test\$3 and with (cod\$3 or \$1 or software) strument\$1 with with operating	-PGPU PAT; O; DE M_TDE	
35	BRS	(Ji	automat\$3 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 with operating	US-PG USPAT JPO; IBM_T	US-PGPUB; USPAT; EPO; 2005/06/14 JPO; DERWENT; 13:14 IBM_TDB
36	BRS	N	automat\$3 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with first with port\$1 with operat\$3	US-PGPUB; USPAT; EP JPO; DERW IBM_TDB	PUB; ; EPO; 2005/06/14 DERWENT; 13:11
37	BRS	8	automat\$6 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 with operating	US-PGP USPAT; JPO; D IBM_TD	-PGPUB; PAT; EPO; 2005/06/14 O; DERWENT; 13:20 M_TDB
38	BRS	ω	automat\$6 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 with operating and serial with number\$1	US-PGPU USPAT; JPO; DE IBM_TDB	US-PGPUB; USPAT; EPO; 2005/06/14 JPO; DERWENT; 13:17 IBM_TDB

	Error Definitio n	Errors	Ref
34			S34
35			S35
36			S36
37			S37
38			S38

40	39	
		Error Definitio n
		Errors
S40	S 3 9	Ref

Type Hits	Search Text automat\$6 with test\$3 test\$3 with (cod\$3 or
41 BRS 1	ו ססיר יר איישו
42 BRS 2	test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 with operating and (ID or identify\$3 or identifier\$1 or serial or identification\$1) with (IC\$1 or integrated adj IC\$1 or motherboard\$1)

42	41	
		Error Definitio n
		Errors
S42	S 4 1	Ref

44	43	
		Error Definitio n
		Errors
S 4 4	S 4 3	Ref

47	6	45	
			Error Definitio n
			Errors
S47	S 4 6	S 4 5	Ref

	Туре	Hits	Search Text	DBs	Time Stamp	Comments
48	BRS		"5511108".PN.	USPAT; USOCR	2005/06/16 09:31	
49	BRS	1	"5432705".PN.	USPAT; USOCR	2005/06/16 09:32	
50	BRS	₽	"4901221".PN.	USPAT; USOCR	2005/06/16 09:32	
51	BRS	Ш	"4760330".PN.	USPAT; USOCR	2005/06/16 09:32	
52	BRS	1	"4718064".PN.	USPAT; USOCR	2005/06/16 09:32	
<u>ა</u>	BRS	1799	(automatic with test\$3 with system\$1).ti.	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16 09:40	
54	BRS	(Ji	(automatic with test\$3 with system\$1).ti. and manufacture\$1 and (ID or identification\$1 or identifier\$1 or serial) with number\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16 09:35	

54	53	52	15	50	49	48	
							Error Definitio n
							Errors
S54	S53	S52	S51	S50	S49	S48	Ref #

	Туре	Hits	Search Text	DBs	Time Stamp	Comments
<u>ບ</u>	BRS	2	automat\$6 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 and (ID or identify\$3 or identification\$1) with (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electron\$6 or electric\$4) and control\$4 with (instruct\$3 or command\$1) and (interface or connection or cable41 or wire\$1) with operat\$3 with system\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16	
56	BRS	H	(automatic with test\$3 with system\$1).ti. and (hi adj pot or hi-pot or high adj potential or hihg-potential)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16	
57	BRS	27	(automatic with test\$3 with system\$1) and (hi adj pot or hi-pot or high adj potential or hihg-potential)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16 09:42	

57	56	ົ ນ	
			Error Definitio n
			Errors
S58	S57	0 0 0	Ref

	Type Hits
56	BRS 28
5 0	BRS 25
60	BRS 5

60	59	58	
			Error Definitio n
			Errors
S61	S 60	S59	Ref

Ty	Туре	Hits	Search Text	DBs	Time Stamp	Comments
61 BRS			(automatic with test\$3 with system\$1) and (hi adj pot or hi-pot or high adj potential or hihg-potential or hipot) and (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electron\$6 or electric\$4) and connect\$3 with (port\$1 or cable41 or wire\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16	
62 BRS			(automatic with test\$3 with system\$1) and (hi adj pot or hi-pot or high adj potential or hipot) with test\$3 and (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electric\$4) and connect\$3 with (port\$1 or cable41 or wire\$1)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16	

62	61	
		Error Definitio n
		Errors
S 63	S 62	Ref

7	65 B	64 B	ω Β	
BRS	BRS	BRS	BRS	Туре
2534	1782	1296	N _.	Hits
324/73.1,538,539,540,541.c cls.	702/57,64,65,119,122,123.c	324/538,539,540,541.ccls.	(automatic with test\$3 with system\$1) and (hi adj pot or hi-pot or high adj potential or hing-potential or hipot) with voltage\$1 with test\$3 and (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electron\$6 or electric\$4) and connect\$3 with (port\$1 or cable41 or wire\$1)	Search Text
US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/06/16 10:33	2005/06/16 09:52	2005/06/16 09:54	2005/06/16	Time Stamp
				Comments

66	65	64	<u>ο</u>	
				Error Definitio n
				Errors
S67	866	S 65	S 64	Ref

	68 BRS 2	67 BRS 3	Type
6284	25	3249	Hits
714/46,47,48,49,50,51,719,	automat\$6 with test\$3 and test\$3 with (cod\$3 or program\$1 or software) and instrument\$1 with port\$1 and (ID or identify\$3 or identification\$1) with (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electron\$6 or electric\$4) and control\$4 with (instruct\$3 or command\$1) and operat\$3 with system\$1	714/46,47,48,49,50,51,719, 720.ccls.	Search Text
US-PGPUB; USPAT; EPO;	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/06/16	2005/06/16	2005/06/16	Time Stamp
			Comments

69	60 88	67	
			Error Definitio n
	,		Errors
S70	S 6 9	S 68	Ref

Туре	Hits	Search Text	DBs	Time Stamp
70 BRS	U	(automatic with test\$3 with system\$1) and (hi adj pot or hi-pot or high adj potential or hihg-potential or hipot) with voltage\$1 with test\$3 and (IC\$1 or integrated adj IC\$1 or motherboard\$1 or electron\$6 or electric\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16
		W.		
71 BRS	15	with DC t or hi-p tential of tential of tential of ltage\$1 of	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	2005/06/16
72 BRS	Н	AC with DC with (hi adj pot or hi-pot or high adj potential or hihg-potential or hipot) with voltage\$1 with test\$3 and	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	2005/06/16
73 BRS	214	automat\$6 with test\$3 and operat\$3 with system\$1 with connect\$3 with port\$1	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	2005/06/16

73	72	71	70	Error Definitio E
S74	873	S72	S71	Errors Ref

76	75	74	
			Error Definitio n
			Errors
S77	S76	S75	Ref

78 B	77 B	ی
BRS	BRS	Туре
4105	N	Hits
324/73.1,511,536,538,539,5 40,541,544,551,.ccls.	automat\$6 with test\$3 and operat\$3 with system\$1 with (interface or communication or connect\$3) and (hi adj pot or hi-pot or high adj pot potential or hipot) with voltage\$1 with test\$3 and (ID or identification\$1 or identification\$1 or with number\$1	Search Text
US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM TDB	US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/06/16 10:34	2005/06/16	Time Stamp
		Comments

6/16/05,
EAST
Version:
2.0.1.4

78	77	
		Error Definitio n
		Errors
S79	S78	Ref

79	
BRS	Туре
2	Hits
automat\$6 with test\$3 and (interface or communication or connect\$3) same operat\$3 with system\$1 with instrument\$1 and (hi adj pot or hi-pot or high adj potential or hipot) with voltage\$1 with test\$3 and (ID or identification\$1 or identifier\$1 or serial) with number\$1	Search Text
US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB	DBs
2005/06/16	Time Stamp Comments
	Comments

79	
·	Error Definitio n
	Errors
0 8 8	Ref